


Control Techniques Americas

7078 Shady Oak Road Eden Prairie, MN 55344-3505 USA

T: +1 952 995-8000 www.controltechniques.com

Document #: PLSCDII201507 **Product Lifecycle Status** Revision Level: A **Commander CDII AC Drives** Date: 07/9/2015

PRODUCT OVERVIEW



CURRENT LIFECYCLE STATUS

The current status of the Commander CDII AC drives is "Obsolete Control Techniques no longer provides repair services or replacement part support. Production capability of Commander CDII drives no longer exist. Upgrade assistance to current product is available.

PENDING LIFECYCLE STATUS CHANGES

None.

REPLACEMENT PRODUCT

The **Unidrive M200** is the recommended replacement product for the Commander CDII products. This latest generation universal AC drive has all of the features of the Commander CDII plus a host of new features and options including communications and additional I/O options.

For full details of the Unidrive M product range or if you need assistance with product selection and conversion please visit the Unidrive M page on the Control Techniques website.

Please visit our Upgrade Assistance page for product upgrade assistance and contact information.



CONTROL TECHNIQUES